

## **BARONA INDIAN CHARTER SCHOOL**

1095 Barona Road, Lakeside, CA 92040 • (619) 443-0948 FAX: (619) 443-7280

BaronaIndianCharterSchool.com

# Governing Board of Directors SPECIAL BOARD MEETING AGENDA July 2, 2021 — 11:00 AM VIRTUAL MEETING VIA ZOOM OR TELEPHONE

Members of the public may make Public Comment at the Board meeting by calling (669) 900-6833 and entering Meeting ID: 984 8716 7237 and Passcode: 477790 or you may use the link <a href="https://bit.ly/3dsgyx3">https://bit.ly/3dsgyx3</a>

## I. Call to Order/Roll Call

- Ray Welch
- > Tawnya Phoenix
- ➤ Mandy Curo Quintero
- > Shirley Ruis, Founder/Member
- > Danthia Gil, Member
- II. Approval of Agenda- any changes to the agenda must be made at this time
- **Public Comment-** Any person may address the Board concerning any item on the agenda and may, at the discretion of the Board, be granted five (5) minutes to make a presentation to the Board at the time a specific item is under discussion. A yellow card must be completed prior to the start of the meeting and given to the Chairperson. Additional time may be granted if circumstances permit. The total time per agenda item devoted to presentations to the Board shall be determined based on the number of speakers wishing to address the board. This time will not exceed 30 minutes unless additional time is granted by a majority of the Board. All presentations shall be heard by the Board prior to the formal discussion of the agenda topic under consideration.

## IV. Action Items

- **A. Approval of Playground Asphalt Repair Project** The Board shall consider the approval of a project by San Diego Asphalt and Recycling Center in Lakeside to grind, repair, and replace the playground area at the school. This project shall also include the installation of two basketball poles and hoops and the painting of a basketball court. This project shall not exceed \$40K.
- **B.** Approval of Purchase from School Outfitters- The Board shall consider the purchase of two basketball poles, backboards, and hoops from School Outfitters for a total not to exceed \$3500.00.

## V. Adjournment

Accommodating Those Individuals with Special Needs—In compliance with the Americans with Disabilities Act, Barona Indian Charter School encourages those with disabilities to participate fully in the public meeting process. If you require special accommodations to attend or participate in our public meeting, contact our office at (619) 443-0948 or ylachappa@barona-nsn.gov by noon of the business day prior to the regular meeting you wish to attend so that we may make every reasonable effort to accommodate you. At least 72 hours prior to each Board meeting, a copy of all available documents supporting the agenda items is available in the school office at 1095 Barona Road, Lakeside CA. You may also request a packet by contacting our office at (619) 443-0948 or ylachappa@barona-nsn.gov.

# **Proposal**

12512 Highway 67 Lakeside, CA 92040 (619) 390-7323 (619) 390-7328 FAX

Date	Proposal #
6/2/2021	2021-65703

Name / Address			Job Location			
Barona Band of Mission Indians 1932 Wildcat Canyon Rd. Lakeside, CA 92040		School Playground Same				
		1	Project			
		Barona School	Playground Asphalt 2021			
P.O. No.	Rep	Referred by	P	hone Number		
65703	MDJ	previous				
		Description		Qty	Cost	Total
Section 1 Using Bartmill Conveying grinder or Bobcat grind, grind at a depth not to exceed 2" over 120 sf and install 2" of 1/2" AR4000 hot mix asphalt. (Approx. 2.0 tons) (Large Cracks)			120	6.00	720.00	
Overlay at a depth not to exceed 1" over no more than 5910 sf using 3/8" Regular AR4000 ho asphalt (Approx. 32.0 tons)			3/8" Regular AR4000 hot mix	5,910	1.10	6,501.00
Section 2 Using Bartmill Conveying grinder or Bobcat grind, grind at a depth not to exceed 2" over 205 sf and install 2" of 1/2" AR4000 hot mix asphalt. (Approx. 3.0 tons) (Large Cracks)			205	6.00	1,230.00	
Overlay at a depth not to exceed 1" over no more than 8742 sf using 3/8" Regular AR4000 hot mit asphalt (Approx. 48.0 tons)			3/8" Regular AR4000 hot mix	8,742	1.10	9,616.20
Section 3 Using Bartmill Conveying grinder or Bobcat grind, grind at a depth not to exceed 2" over 78 sf and install 2" of 1/2" AR4000 hot mix asphalt. (Approx. 1.0 tons) (Large Cracks)				78	6.00	468.00
Overlay at a depth not to exceed 1" over no more than 5331 sf using 3/8" Regular AR4000 hot mix asphalt (Approx. 29.0 tons)			5,331	1.10	5,864.10	
Section 4 Using Bartmill Conveying grinder or Bobcat grind, grind at a depth no install 2" of 1/2" AR4000 hot mix asphalt. (Approx. 2.0 tons) (Large				104	6.00	624.00
Overlay at a depth not to exceed 1" over no more than 3791 sf using 3/8" Regular AR4000 hot asphalt (Approx. 21.0 tons)			3/8" Regular AR4000 hot mix	3,791	1.10	4,170.10

Total
-------

# **Proposal**

12512 Highway 67 Lakeside, CA 92040 (619) 390-7323 (619) 390-7328 FAX

Date	Proposal #
6/2/2021	2021-65703

		_				
Name / Address			Job Location			
Barona Band of Mission Indians 1932 Wildcat Canyon Rd. Lakeside, CA 92040			School Playground Same			
		Project				
	Barona School	Playground	Asphalt 2021			
P.O. No. Rep	Referred by		Р	hone Number		
65703 MDJ	previous					
	Description			Qty	Cost	Total
Stripe parking lot per plans or previous	layout if overlayed or slurry	seal has been	n performed.		1,000.00	1,000.00
After approximately 60 day for curing to	ime, the following additional	work should	l be done		0.00	0.00
Seal coat with Western Colloids Armor Top or equivalent emulsion sealer over no more than 23744 sf. (1 coat, 1 move)			23,744	0.13	3,086.72	
Restripe, per existing layout (Minimum charge)				800.00	800.00	
Above listed bid includes dump fees, but does not include charges for disposal of Petromat, roots, welded wire mesh or rebar. These items are taken by certain landfills but additional charges are incurred.						0.00
This bid does not include rock handling, rock blasting, dewatering, handling or disposal of landscape materials or roots, existing irrigation systems in work area, any utilities not at a proper depth, staking, engineering, traffic control, plans, permits, meters, or inspections. We cannot be held responsible for damage to stucco that has been installed on top of concrete or asphalt being demo. All efforts will be made to not damage, but if stucco is installed directly on surfacing material chances are good that it will come off during demo. Not responsible for sinking asphalt if San Diego Asphalt did not perform the subgrade compaction or installation of base materials.						0.00
Cracks are cracking for a reason. Seismic, weight, roots, asphalt installed on a hill or poor base material installation are some of the most common reasons for cracking. Installing a crack filler may alleviate the initial potential for continued damage of water undercutting, however, this is not a permanent repair and crack filling cannot be guaranteed not to recrack or sink.						0.00

Total
-------

# **Proposal**

12512 Highway 67 Lakeside, CA 92040 (619) 390-7323 (619) 390-7328 FAX

Date	Proposal #
6/2/2021	2021-65703

Name / Address  Barona Band of Mission Indians 1932 Wildcat Canyon Rd. Lakeside, CA 92040			Job Location				
		School Playground Same					
			Project				
		Barona School	Playground	l Asphalt 2021			
P.O. No.	Rep	Referred by		P	hone Numbe	r	
65703	MDJ	previous					
		Description			Qty	Cost	Total
Upon completion of asphalt work, we apply a light sand coat. This s asphalt immediately and limiting the potential for any damages from this sand be removed prior to the seal coat application, we cannot be Seal coating is termed a "wearing course". This means that it is man usage. Excessive traffic and over watering are two of many reasons than the norm. Power steering burns are common and do wear out w cannot be held responsible for people or animals that create damages cannot be held responsible for irrigation that rehydrates or dilutes the responsible for anyone that opens up, drives through or walks throug stains are not warranteed but all efforts are made to insure adherence be applied approximately 30 days from asphalt installation			power steen held liable ufactured to that cause so thin a coup is by entering e wet seal. It is the power of	for any damages.  wear down with eal to wear faster ole of weeks. We ga wet area. We We are not caded areas. Oil			0.00

Total
-------

# **Proposal**

12512 Highway 67 Lakeside, CA 92040 (619) 390-7323 (619) 390-7328 FAX

Date	Proposal #
6/2/2021	2021-65703

Name / Address  Barona Band of Mission Indians 1932 Wildcat Canyon Rd. Lakeside, CA 92040		Job Location				
		School Playground Same				
			Project			
		Barona School	Playground Asphalt 2021			
P.O. No.	Rep	Referred by	Р	hone Numbe	r	
65703	MDJ	previous				
		Description		Qty	Cost	Total
Please note that our bid is based on measurements supplied to us, or take off of plans or from a site visit. Should your company have a contract payoroposal must be used as an exhibit for the services to be performed. An proposal, is either a change order or a new contract must be drawn to ref Should the work be performed due to time logistics it is agreed that autheither in the field or at your corporate head quarters, and will be billed fayoricing structure. Any changes made to the schedule must be made with changes made with less than 3 business days will be assessed a \$500.00 asphalt has been known to germinate grass seed. This is something beyone see grass shoots coming through use Round up or similar weed killer. The Should any additional charges be incurred for Additional Insured requestor Waiver of Subrogation requests, these expenses will be passed on to to order. Exact sample of verbage must be supplied before request to our Insurtherized. We carry the amounts required by the CSLB. Any insurance incur extra expenses that will be passed on to requestor. Asphalt and Cofor a period of (1) year. Please read all limitations or exclusions in other also guaranteed but understand it is a wearing course. Seal should be do for best maintenance based on amount of traffic.			Any work not listed on our reflect the additional scopes. uthorization has been given d fairly and proportional to our within 72 weekday hours. Any 00 administrative fee. Hot beyond our control. Should you. This will not hurt the asphalt. uests, increased liability limits, to the requestor as a change ar Insurance Agent will be ance with higher limits, could. Concrete work are guaranteed ther waivers listed. Seal coat is			

## **Proposal**

12512 Highway 67 Lakeside, CA 92040 (619) 390-7323 (619) 390-7328 FAX

Date	Proposal #			
6/2/2021	2021-65703			

Name / Address				Job Location			
Barona Band of Mission Indians 1932 Wildcat Canyon Rd. Lakeside, CA 92040			School Playground Same				
		1	Project	l			
		Barona School	Playground	l Asphalt 2021			
P.O. No.	Rep	Referred by	Phone Number				
65703	MDJ	previous					
		Description			Qty	Cost	Total
Please note, our payment terms are payment in full upon completion of each phase. Our Accountin Department will get in touch with your Accounting Dept. to ensure any different terms are agreed upon in advance. Should we receive a check from any client that is returned, the maker will be responsible for TWICE the amount of the check and any legal fees and bank charges incurred by San Diego Asphalt. Due to the extra charges that we incur when accepting credit cards, we must add 0.05% (Five percent) for any invoices paid by this method. If for any reason we will not be getting Payment on Completion, our policy is to get a Joint Check Agreement from your company. This is for the materials that we are purchasing. For your protection this agreement states that whe it is time to issue our check we will supply you with the quantity owed to the supplier of materials used. We prefer a separate check cut joint to us and the supplier and the remainder cut to us. This insures you that the materials are paid directly and no Mechanics Liens will be filed on your property due to non-payment of materials.  We do offer a two and a half percent (0.025%) discount of total proposal for deposits of 50% prior to start, except for minimum charge jobs. Interest of 0.05% (Five Percent) per week accruing will be charged to all invoices that are 5 days late. Interest will compound weekly until bill is paid in full, unless arrangements have been made prior to start of work.			t terms are agreed maker will be arges incurred by it cards, we must now will not be om your company. The states that when applier of materials der cut to us. This alled on your consits of 50% prior week accruing will			0.00	

Seal will not adhere to gas or oil.

Power steering turns from stationary vehicles will tear the seal & new asphalt

This estimate is valid for only 30 days

Work requiring "Plant Operation" is to be performed Monday thru Friday excluding Holidays

Our bid is based on Payment on Completion. For Payments that take longer, there are additional charges of 5% every 15 days, unless otherwise stipulated.

	Total	\$34,080.12
Signa	ture	

For assistance, please contact:

Paul Burns Phone: 866-619-5308

Fax: 866-619-4308

paul.burns@schooloutfitters.com

#### www.schooloutfitters.com • PO Box 1367 • Middletown OH 45042-1367

## Quote Summary

Quote #: QUO11286221 Valid through: 07/29/2021

#### Bill to:

Barona Indian Charter School Julie Cushman 1095 Barona Rd

Lakeside CA 92040-1516 USA

Phone: 1 (619) 443-0948

Fax: N/A

Email: jcushman@mybics.org

#### Ship to:

Barona Indian Charter School

Julie Cushman 1095 Barona Rd

Lakeside CA 92040-1516 USA

Phone: 1 (619) 443-0948

Fax: N/A

Email: jcushman@mybics.org

Item	SKU#	Description	Qty.	List	% Off	Price Per Item (including options)	Total Price
1.	BIS-PR52	Heavy-Duty Playground Basketball Hoop w/ Powder-Coated Aluminum Backboard (54" W x 35 1/2" H)  Estimated Delivery: 10 business days after order confirmation	2	\$1,157.00	2%	\$1,129.99	\$2,259.98

## Shipping & Handling Breakdown

 Items Shipping From:
 Shipping Via:
 Service(s) Included:

 Bison Sports
 ABF FREIGHT SYSTEM
 Call Ahead:Julie Cushman 1 (619) 443-0948 ext.300

Product SubTotal: \$2,259.98

Shipping & Handling: \$452.15

Sales Tax: 0.00

Grand Total: \$2,712.13

#### Important Shipping Information

Shipping is tail gate, requiring customer to unload from truck. Lift gate and inside delivery are available for additional charges.

Please remember to inspect your order at the time of delivery. Do not throw away any of the original packaging until inspection is completed. Any missing parts or damages must be reported to customer service at 1-866-619-1776 within 5 business days of delivery.

All quotations are for tailgate delivery, F.O.B. factory, unless otherwise noted.

### **Sales Representative Comments**

Due to the continuous fluctuation with cost of products, increased shortage of raw materials and increased transportation demands, it is important to finalize your ordering needs soon. Please contact us for any assistance needed to proceed with your order.

## California Proposition 65:

California's Proposition 65 requires California consumers to be made aware of special warnings for products that contain chemicals known to the state of California to cause cancer and birth defects or other reproductive harm, if those products expose consumers to such chemicals above certain threshold levels.

We are providing the following warning for anyone buying products that will be shipped to California:

**⚠** Warning: Cancer and Reproduction Harm **�** <u>www.P65Warnings.ca.gov</u>

The safety and well-being of you and your students remains School Outfitters' top priority, and as such, we take all necessary steps to comply with applicable safety and health regulations and uphold our commitment to safety.

Thank you for the opportunity to earn your business.

For Assistance: Paul Burns• Phone: 866-619-5308 • Fax: 866-619-4308 • paul.burns@schooloutfitters.com

Phone: 866-619-5308 Fax: 866-619-4308





## **Item Details**



**Bison Sports** 

www.schooloutfitters.com • 1-800-260-2776 • PO Box 1367 • Middletown OH 45042-1367

## Heavy-Duty Playground Basketball Hoop w/ Powder-Coated Aluminum Backboard (54" W x 35 1/2" H)

Bison's Heavy-Duty Playground Basketball Hoop with Powder-Coated Aluminum Backboard is a durable option for your outdoor court. The pole provides a 48-inch safe-play area and is buried 48 inches into the ground for stability. The fan-shaped, rust-free aluminum backboard has a white, powder-coated finish, support braces and heavy ribbing for maximum rigidity. The steel double-rim goal with no-fail netlock system has a steel backplate and rim supports and accepts nylon (included) or chain nets. It's backed by a 25-year limited warranty on the pole, and a lifetime limited warranty on backboard and unconditional lifetime replacement warranty on goal. Padding not included.

## **Specifications**

Fixed Height or Adjustable:	Fixed height
Portable or Permanent:	Permanent
Backboard Shape :	Fan
Board Material:	Aluminum (white powder-coated finish)
Backboard Dimensions:	54" W x 35 1/2" H
Goal Style:	Front mount (Double-rim)
Goal Material:	Steel
Goal Finish:	Orange, powder-coated finish
Safe-Play Area/Pole Setback:	48"
Pole :	4 1/2" zinc-plated pole
Pole Burial Depth:	48"
Rim Height:	10'
Warranty:	Pole: 25-year limited warranty
	Backboard: lifetime limited warranty
	Goal: unconditional lifetime replacement warranty
Assembly:	Assembled
Product Weight (Lbs):	235

Item	SKU#	Description	Qty.	List	% Off	Price Per Item (including options)	Total Price
1.	BIS-PR52	Heavy-Duty Playground Basketball Hoop w/ Powder-Coated Aluminum Backboard (54" W x 35 1/2" H)	2	\$1,157.00	2%	\$1,129.99	\$2,259.98